	Туре	Ref #	Hits	Search Text
1	IS&R	S1	3	(("6557545") or ("6564793") or ("5960782")).PN.
2	BRS	S2	23	("0351896" "0391274" "0773744" "2819667" "3033190" "3959620" "4382432" "4469019" "4572062" "4852476" "5099821" "5515774" "5715744" "5752497" "5758635" "5787873" "5996572").PN. OR ("6564793").URPN.
3	BRS	S3	14	("0754557" "4553525" "4664026" "4700618" "4962697" "5460159" "5467692" "5673613" "5720272" "5865099" "6058832" "D409436").PN. OR ("6557545").URPN.
4	BRS	S4	10	("3596591" "3938495" "5220747" "5287799" "5746118").PN. OR ("5960782").URPN.
5	IS&R	S6	1682	(126/41r).CCLS.
6	IS&R	S8	844	(126/20).CCLS.
7	IS&R	S9	28	(126/28).CCLS.
8	IS&R	S5	1975	(126/25r).CCLS.
9	BRS	S10	56	("3040651" "3593647" "3809053" "4043312" "4108142" "4276869" "4290408" "4362093" "4403597" "4572062" "4627408" "4662349" "4683867" "4694816").PN. OR ("4773319").URPN.
10	BRS	S11	60 (("0048773" "0324055" "0538469" "0697538" "0774397" "1106555" "1337043" "1475651" "1657683" "2691368" "2727505" "2746378" "2983269" "3326201" "3868943" "3933145" "3982522" "4209006" "4279240" "4607608" "4630593" "4677964" "4727853" "4750469" "D255863").PN. OR ("5031602").URPN.
11	IS&R	S12	0	(126/25rand"firebox").CCLS.
12	BRS	s13	193	126/25r and "firebox"

	DBs		Time St	amp	Comments	Error Definition
1	US-PGPUB; USPA USOCR	AT;	2005/08/19	11:56		
2	US-PGPUB; USPF USOCR	AT;	2005/08/18	09:39	•	
3	US-PGPUB; USPA USOCR	AT;	2005/08/18	09:39		
4	US-PGPUB; USPA USOCR	AT;	2005/08/18	09:40		
5	US-PGPUB; USPA USOCR	AT;	2005/08/18	13:54		
6	US-PGPUB; USPA USOCR	TF;	2005/08/18	13:55		
7	US-PGPUB; USPA USOCR	AT;	2005/08/18	13:55		
8	US-PGPUB; USPA USOCR	; T <i>F</i>	2005/08/18	13:55		
9	US-PGPUB; USPA USOCR	; T <i>P</i>	2005/08/19	07:29	-	,
10	US-PGPUB; USPA USOCR	AT;	2005/08/19			
11	US-PGPUB; USPA USOCR	AT;	2005/08/19			
12	US-PGPUB; USPA USOCR	AT;	2005/08/19	10:09		

	Errors
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	

	Туре	Ref #	Hits	Search Text
13	BRS	S14	105	126/25r and "fire box"
14	BRS	S15	23	126/25r and "fire box" and seal\$
15	BRS	S16	1	126/25r and "fire box" near seal\$
16	IS&R	S17	374	(126/33).CCLS.
17	IS&R	S18	1975	(126/25r).CCLS.
18	IS&R	S19	1682	(126/41r).CCLS.
19	IS&R	S20	844	(126/20).CCLS.
20	IS&R	S21	28	(126/28).CCLS.
21	BRS	S22	86	"baffle plate" and (S19 or S20 or S21 or S18 or S17)
22	BRS	S23	9	S22 and hood

	I	DBs	Time	Stamp	Comments	Error Definition
13	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:00		
14	US-PGPUB; USOCR		2005/08/	19 11:00		
15	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:00		
16	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:57		
17	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:58		
18	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:58		
19	US-PGPUB; USOCR	USPAT;	2005/08/	ļ9 11:58		
20	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:58		
21	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:59		
22	US-PGPUB; USOCR	USPAT;	2005/08/	19 11:59		

	Errors
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	